

Report Prepared for: Jane and John Sample

# Home Inspection Report



123 Sample Street



Home Inspections Ltd.  
Jeanine Reiss

## GENERAL INFORMATION

---

### **Inspection Address**

**Street:** 123 Sample Street, Sample Town

### **Inspection Details**

**Inspection Date:** July 24, 2012

**Report Date:** July 24, 2012

**Weather Conditions:** sunny

**Temperature:** 28 degrees C

**Present during inspection:** buyer and tenant

**Building Occupied:** yes occupied and fully furnished

### **Building Details**

**Date Built:** 1978

**Approximate Age:** 34 years

**Approximate Area:** 3750 Sq. Ft.

**Entrance Faces:** Southeast

**Nearest Fire Hydrant:** Within 100 meters

### **Inspected By**

**Name:** Jeanine Reiss

CAHPI(BC) Member

CPBC Lic. # 58372

### **Company Information**

**Company:** FYI Home inspections Ltd, 9090 Shanks Road, Lake Country, BC, V4V 1M4

**Phone:** 250-766-1984      **Cell:** 250-864-4054

**Email:** jeanine@fyihomeinspections.ca

**Web Site:** www.fyihomeinspections.ca



## PURPOSE AND SCOPE

*It should be noted that a standard pre-purchase inspection is a visual assessment of the condition of the residence at the time of inspection. The inspection and inspection report are offered as an opinion only. Although every reasonable effort is made to discover and correctly interpret indications of previous or ongoing defects that may be present, it must be understood that no guarantee is implied nor responsibility assumed by the inspector or inspection company, for the actual condition of the building or property being examined. Additional information as to inspection standards is included at the end of the report.*

*This firm endeavors to perform all inspections in substantial compliance with the standards of practice of the Canadian Association of Home and Property Inspectors (CAHPI). As such, our inspectors inspect the readily accessible and installed components and systems of a home as outlined below:*

*This report contains observations of those systems and components that are, in the professional opinion of the inspector authoring this report, significantly deficient or are near the end of their expected service life. If the cause for the deficiency is not readily apparent, the suspected cause or reason why the system or component is at or near end of expected service life is reported, and recommendations for correction or monitoring are made as appropriate. When systems or components designated for inspection in the CAHPI standards are present but are not inspected, the reason the item was not inspected is reported as well.*

## GENERAL LIMITATIONS AND EXCLUSIONS

*The CAHPI Standards of Practice are applicable to buildings with four or fewer dwelling units and their garages or carports. They are the bare minimum standard for a home inspection, are not technically exhaustive and do not identify concealed conditions or latent defects. Inspectors are NOT required to determine the condition of any system or component that is not readily accessible; the remaining service life of any system or component; the strength, adequacy, effectiveness or efficiency of any system or component; causes of any condition or deficiency; methods materials or cost of corrections; future conditions including but not limited to failure of systems and components; the suitability of the property for any specialized use; compliance with regulatory codes, regulations, laws or ordinances; the market value of the property or its marketability; the advisability of the purchase of the property; the presence of potentially hazardous plants or animals including but not limited to wood destroying organisms or diseases harmful to humans; the presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water or air; the effectiveness of any system installed or methods utilized to control or remove suspected hazardous substances; the operating costs of any systems or components and the acoustical properties of any systems or components.*

*Inspectors are NOT required to operate any system or component that is shut down or otherwise inoperable; any system or component which does not respond to normal operating controls or any shut off valves.*

*Inspectors are NOT required to offer or perform any act or service contrary to law; offer or perform engineering services or work in any trade or professional service other than home inspection.*

*We DO NOT offer or provide warranties or guarantees of any kind unless clearly explained and agreed to by both parties in a formal pre-inspection agreement.*

*Inspectors are NOT required to inspect underground items including, but not limited to underground storage tanks or other underground indications of their presence, whether abandoned or active; systems or components that are not installed; decorative items; systems or components that are in areas not entered in accordance with the CAHPI Standards of Practice; detached structures other than carports or garages; common elements or common areas in multi-unit housing, such as condominium properties or cooperative housing.*

*Inspectors are NOT required to perform any procedure or operation which will, in the opinion of the inspector, likely be dangerous to the inspector or others or damage the property, its systems or components; move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice or debris or dismantle any system or component, except as explicitly required by the CAHPI Standards of Practice.*

*Our inspectors are NOT required to enter under-floor crawlspaces or attics that are not readily accessible nor any area which will, in the opinion of the inspector, likely be dangerous to the inspector or others persons or damage the property or its systems or components.*

*We do not limit our inspectors from examining other systems and components or including other inspection services. Likewise, if the inspector is qualified and willing to do so, an inspector may specify the type of repairs to be made. The inspector may also exclude those systems or components that a client specifically requests not be included within the scope of the inspection. If systems or components are excluded at the request of the client they are listed herein.*

# STRUCTURAL SYSTEM

*In accordance with the CAHPI Standards of Practice pertaining to Structural Systems, this report describes the foundation, floor, wall, ceiling and roof structures and the method used to inspect any accessible attics and under floor crawlspace areas. Inspectors are required to inspect and probe the structural components of the home, including the foundation and framing, where deterioration is suspected or where clear indications of possible deterioration exist.*

## COMPONENT DESCRIPTIONS

### **Construction Type**

**Structure Type:** residence is a walk-out rancher with a basement suite

**Attached - Detached:** detached

**Construction Type:** wood frame

**Residence Style:** single-family dwelling

**Bedrooms:** five

**Kitchens:** two

**Bathrooms:** three

**Supporting Foundation:** Partial daylight basement with remainder being a conditioned concrete crawlspace

### **Building Foundation**

**Foundation Type:** a combination basement-crawlspace

**Foundation Material:** poured concrete

**Condition:** satisfactory condition – minor shrinkage and settlement cracking

**Structural movement:** normal settlement

**Support Columns:** wood and steel beam support

**Condition:** satisfactory condition

### **Wall Structure**

**Wall Studs:** 2 by 4 and 2 by 6

**Wall On-Center:** 16-inch

**Wall Sheathing:** plywood sheathing

**Condition:** satisfactory condition – for what could be seen

### **Floor Structure**

**Floor Framing:** platform framing

**Floor Joists:** 2 by 10 joists

**Floor On-Center:** 16-inch

**Floor Sheathing:** plywood sheathing

**Condition:** satisfactory condition

### ***Roof Structure***

**Roof Assembly Type:** a combination of rafters and manufactured truss

**Size:** 2 by 4

**Rafters:** 2 x 10

**Rafter/Support On-Center:** 24-inch

**Roof Sheathing:** oriented strand board (OSB)

**Condition:** satisfactory condition

### ***Crawlspace Entrance Inspection***

**Inspection Method:** entered crawlspace

**Condition:** satisfactory condition, dry and conditioned

**Entrance Location:** from basement

### ***Attic Entrance Inspection***

**Inspection Method:** entered attic

**Entrance Location:** ceiling hatch in the laundry room

## **OBSERVATIONS**

All structure observed during inspection seem to be in satisfactory condition. No deterioration, warping, displacement, or moisture damage was noted.

The basement and crawlspace were found to be warm and dry. No moisture egress was noted at the time of inspection.

The concrete foundation viewable in the crawl space shows random signs of minor settlement and shrinkage cracks. All residential foundations settle to some degree over the lifespan of the home. Such movement is not considered structurally significant. It appears that some of the cracks were sealed early on and do not show signs of new movement. This foundation has probably reached final compaction, and unless something significant happens, like an unforeseen major flood or seismic activity, it is not likely to settle significantly more.



Roof structure



Older sealed crack, no new movement observed.

*Probing is not done when doing so will damage finished surfaces, when no visible deterioration exists and if doing so requires our inspectors to be licensed pest control operators (PCO), unless the inspector involved is so licensed. Inspectors are NOT required to offer an opinion as to the structural adequacy of any structural systems or components or provide architectural services or an engineering or structural analysis of any kind.*

## EXTERIOR

In accordance with the CAHPI Standards of Practice pertaining to Exteriors, this report describes the exterior wall coverings and trim. Inspectors are required to inspect the exterior wall coverings, flashings, trim, all exterior doors, the stoops, steps porches and their associated railings, any attached decks and balconies and eaves, soffits and fascias accessible from ground level.

### COMPONENT DESCRIPTIONS

#### **Building Exterior**

**Wall Surface Material:** stucco

**Condition:** satisfactory condition

**Flashing:** aluminum and vinyl

**Condition:** satisfactory condition

**Wall Trim:** aluminum and vinyl

**Condition:** satisfactory condition

**Entry Door Types:** metal clad insulated, and metal-clad with glass panel inserts

**Condition:** satisfactory condition

**Garage Door:** no doors

**Condition:** N/A

**Eave Type:** normal overhang

**Condition:** satisfactory condition

**Soffit Type:** enclosed and vented aluminum soffit material

**Condition:** satisfactory condition

**Facia Type:** wood

**Facia condition:** satisfactory condition



#### **Sun deck:**

**Sun deck type:** Poured concrete

**Sun deck location:** on the southern exterior

**Condition:** satisfactory condition

**Sun deck steps/stairs:** sun deck to pathway, sun deck to pool area

**Condition:** satisfactory condition

**Sun deck railing:** wrought iron

**Porch:**

**Porch type:** Poured concrete

**Porch location:** Main entry at the southern exterior

**Condition:** satisfactory condition

**Porch steps/stairs:** two steps up

**Condition:** satisfactory condition

**Porch railing:** none, OK

**Basement entry**

The basement can be entered by an exterior entry. There are concrete stairs leading to the basement. A floor drain is present at the bottom of the basement stairs. While the stair case is in satisfactory condition, it is suggested hand rail as well as a guard rail be installed for safety reasons.



**Drives and walkways**

**Driveway Types:** asphalt

**Condition:** satisfactory condition, freshly re-sealed

**Walkway Type:** poured concrete

**Walkway condition:** satisfactory condition

**Fences and gates**

**Type:** Property perimeter is fenced with pole fencing with aluminum farm gates. Wrought iron and wood fencing around pool area. Two wrought iron gates to pool.

**Condition:** satisfactory condition



## **Slope and Drainage**

**Direction of Lot Slope:** Relatively flat lot, which slopes away from the home on all sides

**Condition:** satisfactory condition

**Drainage Piping:** PVC and Big -O

**Drains Connected to:** to swale area

**Gutters / Downspouts Drain:** Big-O and onto grade, away from home<sup>1</sup>

**Vegetation:** There is some vegetation against the southern and eastern sides of the foundation and home.

## **Retaining Walls**

**Retaining Wall Type:** none

## **Gas meter**

Present at northern exterior, satisfactory condition. Sealed.

## **Hose bibs**

All (three) exterior hose bibs are observed to be frost-free.

*Inspectors are NOT required to inspect or report on the presence or condition of recreational facilities, outbuildings, seawalls, break-walls and docks, window and door screening, shutters, awnings or similar seasonal accessories.*

## **OBSERVATIONS**

Parging (a thin coat of mortar type material) was applied to the exterior concrete foundation and to the sides of the various concrete stairs around the exterior of the home.. While most of the parging is in good shape, some of it, in particular near the concrete steps leading to the front sun deck, is starting to flake and peel. Parging is applied mostly for esthetic reasons only, and flaking usually does not reflect on the quality of the foundation or concrete work.



The exterior woodwork and painted surfaces appear in satisfactory condition. It is important that all exposed wood surfaces are kept well protected to ensure a maximum service life. Subsequent paint maintenance can be carried out as the usual signs of failure such as cracking, peeling or blistering of the painted surface become evident. Typically this would occur at intervals of two to five years.

Joints between dissimilar materials, such as stucco to window and door frames, stucco to wall penetrations such as hose bibs, etc., are currently nicely caulked and sealed. It is important to maintain sealing and caulking in order to prevent moisture and insect infiltration into the structure.

---

<sup>1</sup> The drains 'daylight' or empty onto the surface of the yard well clear of the foundation.

Most trees, plants and shrubs are well away from the dwelling. However, there is some vegetation against the southern and eastern sides of the foundation and home. Having plants so close to the home can lead to insect or vermin infestation, as well as moisture penetration, which can result in damage to the foundation and walls. While this vegetation seems to pose no problems to the dwelling at the time of inspection, I recommend trimming back all vegetation around the perimeter of the home, leaving about 4 inches of clearance between vegetation and the side of the dwelling. Continue to monitor for signs of moisture or insect issues as part of your regular home maintenance regimen.



## ROOF SYSTEM

---

*In accordance with the CAHPI Standards of Practice pertaining to Roof Systems, this report describes the roof coverings and the method used to inspect the roof. Inspectors are required to inspect the roof covering, roof drainage systems, flashings, skylights, chimneys and roof penetrations.*

### COMPONENT DESCRIPTIONS

New roofing was installed including sheathing, flashings, and roof vents in 2007

#### **Roof Covering**

**Roof Inspected:** by walking the entire surface

**Roof Slope:** pitched

**Roof Style:** hip

**Roofing Materials:** asphalt shingles/fiberglass shingles, installed 2007

**Material Condition:** satisfactory condition

#### **Flashing**

**Flashing Type:** metal

**Flashing Locations:** roof valleys, roof to wall intersections and base of the chimney(s)

**Condition:** satisfactory condition

#### **Gutters Downspouts**

**Gutter / Downspout Type:** aluminum

**Gutters / Downspouts Drain:** onto grade and perimeter drains

**Condition:** satisfactory condition, very clean

#### **Skylights**

**Skylight Type:** none

#### **Chimneys**

**Chimneys Type:** One masonry stack, two flues. One B-vent for furnaces

**Fireplace Stove Locations:** wood burning fireplace in family room, woodstove in basement

**Condition:** satisfactory condition, for what could be seen

## OBSERVATIONS

According to the owner this roof is from 2007. Typical life expectancy of asphalt/fibreglass shingles is generally 30-40 years depending of the quality of product. The roof is aging normally.



Roof penetrations (plumbing stack, roof vents, etc) seem to be in satisfactory condition from what could be seen. Roof penetrations should be checked for cracks and breaks, proper caulking as part of regular roof maintenance. Exposed nails should be sealed.

Some of the down spouts go under-ground, others empty onto grade. It is suggested that gutters that empty onto grade are extended at least 4 to 6 feet away from the home and foundation to prevent possible water issues.



Consider installing chimney caps to deter unwanted critters and protect from water penetration.

*Inspectors are NOT required to inspect antennae, interiors of chimneys or flues that are not readily accessible or other installed accessory items.*

## PLUMBING SYSTEM

*In accordance with the CAHPI Standards of Practice pertaining to Plumbing Systems, this report describes the water supply, drain, waste and vent piping materials and the water heating equipment, energy source and location of the main water and main fuel shut-off valves, when readily viewable or known. Inspectors are required to inspect the interior water supply and distribution systems, all fixtures and faucets, the drain waste and vent systems (including all fixtures for conveying waste), the water heating equipment (vent systems, flues and chimneys of water heaters or boiler equipment), fuel storage and distributions systems for water heaters and/or boiler equipment and drainage sumps, sump pumps and associated piping.*

### COMPONENT DESCRIPTIONS

The inspection of the plumbing system includes checking all faucets and fixtures for cross-connection and leaks. Cross-contamination issues are also included as well as pressure, functional flow and functional drainage.

#### **Supply and Piping**

**Supply and Waste System:** municipal supply with a private waste system

**Service Piping Size:** 3/4-inch

**Service Piping Type:** copper

**Branch Piping Size:** 1/2-inch

**Branch Piping Type:** Mainly copper, some plastic

**Condition:** satisfactory condition

**Fixtures/Faucets Condition:** satisfactory

**Supports/Insulation Condition:** satisfactory, where it can be seen

**Functional Flow:** satisfactory

**Function Drainage:** satisfactory

**Waste Piping:** ABS / cast iron

**Condition:** satisfactory condition<sup>1</sup>

**Vent Piping:** ABS plastic, cast iron, copper

**Condition:** seems to be in satisfactory condition

#### **Water Heater**

**Water Heater Type:** one conventional storage tank

**Water Heater Energy Source:** electricity

**Capacity:** 284 Liters

**Year of Manufacture:** 2007 - The life expectancy of an electric water heater is 8 to 10 years.

---

<sup>1</sup> Only visible DWV piping is inspected. The inspection is primarily for leaks and flow. For a more intensive inspection a consultation with a licensed plumbing contractor is recommended.

**Make:** John wood pro series

**Model:** JW805DE145

**Serial No.:** U0704526267

**Water Heater Location:** basement

**Condition:** satisfactory condition

**Water Heater Vented:** N/A

**Shut Off Location:** at the water heater

**Automatic Safety Controls (TPR) Condition:** satisfactory condition

### ***Water Controls and Drains***

**Main Water Shut Off Location:** basement near hot water heater

**Main Water Regulator Location:** basement

**Waste Clean-out Locations:** present in various locations

**Main Floor Drain Location:** basement



Main water shut-off

### ***Kitchen plumbing, main***

**Supply Piping:** copper

No active leaks observed. Kitchen sink was filled and emptied. Water pressure and drainage seem adequate. Water fixtures seem to be in satisfactory condition. Appropriate caulking was observed.

### ***Bathroom plumbing, Hallway, 4-piece***

**Supply plumbing:** copper

No active leaks observed. Bath tub and sinks were filled and emptied. Water pressure and drainage seem adequate. Water fixtures seem to be in satisfactory condition. Appropriate caulking was observed. Toilet flush was observed and found adequate.

This bathroom is equipped with a Toto toilet. The manufacturer claims you can flush a golf ball without clogging the toilet. I am not suggesting you try this, but they are indeed hard to clog. No leaks observed. No movement of toilet tank or bowl.

### ***Bathroom plumbing, master bedroom, 3-piece en suite***

**Supply plumbing:** copper

No active leaks observed. Bathtub and sink were filled and emptied. Water pressure and drainage seem adequate. Water fixtures seem to be in satisfactory condition. Appropriate caulking was observed. Toilet flush was observed and found adequate. No leaks observed. No movement of toilet or bowl.

## **Laundry room plumbing**

**Supply Piping:** copper

No active leaks were observed. Laundry sink was filled and emptied. Water pressure and drainage seem adequate. Water fixtures seem to be in satisfactory condition.

## **Kitchen plumbing - Basement**

**Supply Piping:** copper

No active leaks observed. Kitchen sink was filled and emptied. Water pressure and drainage seem adequate. Water fixtures seem to be in satisfactory condition. Appropriate caulking was observed.


## **Bathroom plumbing, basement, 3-piece**

**Supply plumbing:** copper

No active leaks observed. Bathtub and sink were filled and emptied. Water pressure and drainage seem adequate. Water fixtures seem to be in satisfactory condition. Appropriate caulking was observed. Toilet flush was observed and found adequate. No leaks observed. No movement of toilet tank or bowl.

## **OBSERVATIONS**

The trap seal depth of the p-trap under the basement kitchen sink is excessive. While no drainage problems were observed at the time of inspection, a trap seal depth of more than approx. 4 inches can cause sludge and waste to build-up resulting in slow draining and clogging. I recommend calling a licensed plumber to remedy the situation.



The washing machine has rubber hoses. I recommend replacing these hoses with stainless steel braided hoses. These reduce the likelihood of damage from a hose rupture due to a weak hose.

When reference is made to the type of plumbing, the comment relies on a visual observation, seller statements, the presence or absence of a water bond, and what may be present in the way of notification in the electrical service panel. There is no non-invasive way to determine what is behind a closed wall. For example, when copper plumbing is identified, copper piping protrudes from the walls behind plumbing fixtures. If client requires absolute knowledge as to the type of plumbing throughout the home, then a consultation with a licensed plumbing contractor is recommended. Please note: Inspectors are not required to determine the source of the water supply or operate any valve except water closet flush valves, fixture faucets, and hose bibs. Solar systems, septic systems, wells, filters, conditioners, yard watering systems and fire sprinkler systems are not part of this inspection and are further not required of the home

inspector. Please note: Water stop valves and overflows are not checked for function in the course of a home inspection. Fixtures and trim are observed for function only and not for cosmetic value.

*Inspectors are NOT required to inspect the connections for clothes washing machines, interiors of flues or chimneys when not readily accessible, wells or well pumps, equipment associated with water storage, water conditioning equipment, solar water heating components or systems, fire sprinkler or irrigation systems or private waste disposal (septic) systems. Additionally, inspectors are not required to operate safety valves or shut-off valves of any kind. Inspectors DO NOT determine the quantity or quality of water supplies or whether water supply and waste disposal systems are public or private.*

# ELECTRICAL SYSTEM

*In accordance with the CAHPI standard of practice pertaining to Electrical Systems, this report describes the amperage and voltage rating of the service, the location of the main disconnect and any sub panel(s), the presence of solid conductor aluminum branch circuit wiring and the absence of smoke detectors. Inspectors are required to inspect the viewable portions of the service drop from the utility to the house, the service entrance conductors, cables and raceways, the service equipment and main disconnects, the service grounding, the interior components of the service panels and sub panels, the conductors, the over-current protection devices (fuses or breakers), ground fault circuit interrupters and a representative number of installed lighting fixtures, switches and receptacles.*

## COMPONENT DESCRIPTIONS

### **Service Entry**

**Service Drop Type:** underground service lateral

**Service Entry Conductor:** copper

**Service Ground Conductor:** stranded copper

**Service Ground Location:** water pipe inside the building, and ground rod

**Meter Location:** north side of the residence

### **Main Disconnect**

**Main Disconnect Type:** lever shutoff, fuses

**Main Disconnect Rating:** 350 amp

**Main Disconnect Location:** inside the service entrance panel

### **Main Panel**

**Service Entrance Panel Location:** Basement

**Panel Type:** Federal Pacific X 2

**Panel Style:** breaker system

**Amperage Rating:** 200 amps X 2

**Voltage Rating:** 120/240 volts

**Final Service Rating:** 350 amp

### **Distribution Wiring**

**Wiring Type:** non-metallic sheathed cable (Romex)

**Wiring Conductors:** copper

**GFCI Locations:** Bathroom(s) and Exterior of the building

### **Smoke Alarm Detectors**

**Smoke Alarms:** 2 hard-wired alarms found

## **Sub Panel**

**Sub Panel Location:** Swimming pool and hot tub each have sub panel

**Sub Panel Type:** Federal Pacific

**Sub Panel Style:** breaker system

**Sub Panel Amperage Rating:** 50 amps

**Sub Panel Voltage Rating:** 120/240 volt

**Condition:** Pool - satisfactory condition. Hot Tub - satisfactory condition

## **OBSERVATIONS**

This dwelling has a 350 amp fused service box, which feeds two 200 amp rated distribution panels. Sub panels are further located at the pool and near hot tub.

There are open cable openings in the sides of the service panel box where cables may have been removed. When wiring is removed from a panel, these openings are supposed to be plugged with approved devices. I recommend having this corrected by a licensed electrician.


The main distribution panels appear to have some room for future upgrades or additions to the system. All breakers are clearly labeled.

A representative number of switches and receptacles that are readily accessible are tested for function. Determination of adequacy of electrical panels and current capacity are not within the scope of this report. Low voltage systems, stereos, intercoms, vacuum systems, security systems or other low voltage systems are not inspected and are not within the scope of a home inspection.

The smoke alarms were tested and found to be working at the time of inspection.

Receptacle in main floor hallway by the bedrooms is dead. Recommendation: Have issue remedied by licensed electrician.

This home used to have an electric attic fan on the roof. The fan has since been disconnected, but the electrical feed for this unit is still present and live in the attic. These wires need to be appropriately capped off in a safe electrical housing with cover for possible future use. Note: the moisture issue that can be seen in the upper corner of the picture was dealt with when the roof was replaced in 2007.



## HEATING SYSTEM

*In accordance with the CAHPI Standards of Practice pertaining to Heating Systems, this report describes the energy source and the distinguishing characteristics of the heating system(s). Inspectors are required to inspect the installed heating equipment and associated vent systems, flues and chimneys.*

### COMPONENT DESCRIPTIONS

Heating units are tested using normal operating controls. Readily accessible inspection doors are opened for interior viewing unless the doors are taped shut or otherwise sealed. Inspector will not break seals as a new seal is required upon completion of the inspection.

#### **Heating Systems**

**Type of Heating System:** Two natural gas forced air furnaces

**Heating System Access:** furnaces are in basement

**Location Electric Safety Switch:** at the units

**Type of Thermostats:** two programmable

**Location of Thermostats:** main floor hall and family room

#### **Furnaces**

**Make:** two Lennox Whisperheat, mid-efficiency furnaces

**Year of manufacture:** both 1992. Under normal circumstances a furnace should last about 20 years.

**Last service date:** April 16<sup>th</sup> 2012

**Model:** G20QZE-75-C1

**BTU:** 75.000

**Serial:** 6392J40187 and 6392F29610

**Condition:** both furnaces started as expected using normal operating controls.

#### **Fuel and Controls**

**Fuel Shut Off Location:** at the furnace

**Automatic Safety Controls (TPR) Condition:** satisfactory condition

#### **Intake:**

**Intake Through:** through wall at east side of dwelling

**Condition:** satisfactory condition

## **Exhaust**

**Exhaust Vent Type:** double-wall metal

**Exhausts Through:** vents up through the roof

**Condition:** satisfactory condition

**Flue Shared with Hot Water:** no

## **Ducting Ventilation**

**Type of Ducting:** galvanized sheet metal

**Condition:** satisfactory condition - for what could be seen

**Type of Return Ducting:** through framing and galvanized steel sheet metal

**Condition:** satisfactory condition - for what could be seen

## **Air Filter**

**Location:** return intake before furnace

**Type:** fiberglass cartridge

**Condition:** satisfactory condition

**Width:** 16" **Height:** 25" **Depth:** 1"

## **OBSERVATIONS**

The normal sequence of operating modes was executed with no obvious defects noted.

All rooms were checked for a heat source (delivery register) with no defects noted.

To maintain air flow and quality it is recommended that furnace filters are cleaned or replaced no less than four times a year.

The presence of two humidifiers near the furnaces was noted. They are programmable by the same thermostats that run the central air conditioners/furnaces. The humidifiers were shut off at the time of inspection and not tested.



*Inspectors are NOT required to inspect the interiors of flues or chimneys when not readily accessible, the heat exchanger(s) of boilers or furnaces, humidifiers or dehumidifiers, electronic air cleaners or any solar space heating system(s). Inspectors are also NOT required to determine the adequacy of the heating system or distribution/balance of heat throughout the home.*

# AIR CONDITIONING SYSTEMS

---

*In accordance with the CAHPI standards of practice pertaining to Air Conditioning Systems. Inspectors are required to inspect only installed central or through-wall air conditioning units and to describe their distinguishing characteristics and energy source.*

## COMPONENT DESCRIPTIONS

### **System Description**

**Type of system:** two central air conditioners

**Energy source:** electricity

**Exchange Method:** air source

**Make:** Lennox

**Year of Manufacture:** both units are from 2006. Life expectancy of a central air-conditioner is 15 – 20 years.

**Model:** MNXP 15-030-230-01

**Serial:** 5806J22398 and 5806J15343

### **Air Handler Evaporator**

**Inside Unit Location:** at the furnace

### **Coil Condenser**

**Outside Unit Location:** exterior north side of the building on a concrete slab

### **Thermostat**

**Type:** programmable

**Locations:** main floor hall and family room

**Location of Cutoff:** within sight of the unit

### **Air Ducting**

**Type of Ducting:** galvanized sheet metal

**Condition:** satisfactory condition - for what could be seen

**Type of Return Ducting:** through framing and galvanized steel sheet metal

**Condition:** satisfactory condition - for what could be seen

## OBSERVATIONS

The normal sequence of operating modes was executed with no obvious defects noted.

All rooms were checked for a cooling source (delivery register) and no defects were observed.

The thermostat as well as the ductwork for the air conditioning is the same as for the heating function of the home.

Heating and air conditioning system(s) last longer and perform more efficiently when serviced seasonally.



*Inspectors are NOT required to inspect electronic air cleaner filters or determine the adequacy of the air conditioning system or whether it is properly balanced. We DO NOT operate any cooling system equipment, including the cooling cycle of heat pumps, when the exterior temperature is less than 60°F.*

# INTERIOR

In accordance with the CAHPI Standards of Practice pertaining to Interiors, there is NO requirement for the report to describe any interior components or finishes. Inspectors are required to inspect walls, ceilings and floors, steps, stairways and railings, countertops and a representative number of cabinets, a representative number of doors and windows and the garage doors and automatic garage operators.

## COMPONENT DESCRIPTIONS

### **Room Interior**

**Wall Surface Type:** drywall

**Ceiling Surface Type:** drywall with "pop corn" texture

**Flooring Type:** hard wood, ceramic or porcelain tile, wall to wall carpet,

### **Steps, stairways, railings**

**Stairways location:** Foyer to main floor, foyer to basement

**Railing:** absent

### **Kitchen details, main kitchen**

**Kitchen Flooring Material:** ceramic or porcelain tile

**Kitchen Counter Top Type:** quartz

**Kitchen Cabinet Type:** face frame

**Sink/ basin:** stainless steel double sink

**Plumbing Fixtures:** chrome

### **Bathroom details, hallway, 4-piece**

**Bathroom Flooring Material:** ceramic or porcelain tile

**Bathroom Counter Top Type:** granite

**Bathroom Cabinet Type:** face frame

**Sink/ basin:** two side-by-side porcelain sinks

**Shower/tub:** one-piece fiberglass bath tub and surround

**Plumbing Fixtures:** chrome

**Condition:** satisfactory condition

### **Bathroom details, master bedroom 3-piece en suite**

**Bathroom Flooring Material:** ceramic or porcelain tile

**Bathroom Counter Top Type:** granite

**Bathroom Cabinet Type:** face frame



**Sink/ basin:** porcelain

**Shower/tub:** two-piece fiberglass bath tub and surround

**Plumbing Fixtures:** chrome

**Condition:** satisfactory condition

### ***Kitchen details, basement***

**Kitchen Flooring Material:** ceramic or porcelain tile

**Kitchen Counter Top Type:** laminate

**Kitchen Cabinet Type:** frameless

**Sink/ basin:** stainless steel double sink

**Plumbing Fixtures:** chrome

**Condition:** satisfactory condition



### ***Bathroom details, basement, 3-piece***

**Bathroom Flooring Material:** ceramic or porcelain tile

**Bathroom Counter Top Type:** polymer resin

**Bathroom Cabinet Type:** frameless

**Sink/ basin:** polymer resin

**Shower/tub:** freestanding fiberglass bath tub

**Plumbing Fixtures:** chrome

**Condition:** satisfactory condition

### ***Windows and Doors***

**Window Frame Type:** vinyl

**Window Pane Type:** double glazed

**Condition:** satisfactory condition, all window locks are operable. Some windows have a dust/mildew build-up. This can be cleaned up with a water and bleach solution.

**Safety Glazing:** None

**Security Bar Locations:** none

**Inside Door Type:** hollow core wood panel

**Condition:** satisfactory condition


**Garage Walk-through Door:** n/a, garage is not attached to home



## OBSERVATIONS

There are minor wall and trim blemishes throughout the home that are of no significance other than cosmetic.

There is a slight crack in the ceiling between the living room and the main hallway. The home owner mentioned the crack gets a bit worse in fall, and then greatly reduces in spring. Because the crack seems to be seasonal, some form of very slight truss uplift in the attic is suspected. Truss uplift is caused when there is a temperature and moisture difference between the top chord and the bottom chord of a truss. The wood in the top chord expands with absorbed moisture from cold winter air in the attic space, while the bottom chord remains stable because it is protected by the insulation and the heat coming from the house. As the top chord expands it forces the bottom chord to arch up. Structurally this is not a problem, but in this case it does produce a slight seasonal crack in the tape joint of the ceiling drywall. If the crack is found esthetically displeasing I suggest installing a nice trim over the crack, which will cover the contracting and expanding crack throughout the seasons.



The interior staircase leading to the main floor, as well as the staircase leading to the basement, does not have a hand rail. While acceptable for the era of the home, it is recommended for safety reasons that stairs with more than three risers to have hand railings installed.

There is a slight floor squeak in the stairway leading to the main floor. Squeaks are usually the result of improperly installed or inadequately secured sub flooring. The squeaks may be annoying but are normally not structurally significant.

# APPLIANCES

---

## COMPONENT DESCRIPTIONS

### **Range**

**Range Style:** Built-in glass range top, 5 burners and integral exhaust fan

**Fuel:** Electric

**Make:** Jennair

**Model:** JLD4536WS00

**Serial:** DY3543343

### **Oven**

**Oven Style:** built-in oven

**Fuel:** Electric

**Make:** Kenmore Elite

**Model:** not viewable

**Serial:** not viewable

### **Refrigerator**

**Refrigerator Style:** Up/down refrigerator/freezer

**Fuel:** Electric

**Make:** Kenmore Elite

**Model:** 59677532600

**Serial:** 11545203LG

### **Dishwasher**

**Dishwasher Style:** Built-in

**Make:** Kenmore Elite

**Model:** 66513792K603

**Serial:** FU2001008

### **Built-in Vacuum**

**Make:** Modern Day

**Built-in Vacuum Location:** basement

**Model:** not viewable

**Serial:** not viewable

### ***Washing Machine***

**Washing Machine Type:** an electric front-loading clothes washer

**Make:** Kenmore Elite

**Model:** 45872402

**Serial:** CST0209665

### ***Clothes Dryer***

**Clothes Dryer Type:** an electric front-loading clothes dryer

**Make:** Kenmore Elite

**Model:** C85872401

**Serial:** MUD0801221

### ***Range - basement***

**Range Style:** Freestanding stove with oven

**Fuel:** Electric

**Make:** Kenmore

**Model:** C9790560222

**Serial:** UF12185624

### ***Oven - basement***

**Oven Style:** Integral to the range

**Fuel:** Electric

### ***Refrigerator - basement***

**Refrigerator Style:** Up/down freezer/refrigerator

**Fuel:** Electric

**Make:** Frigidaire

**Model:** FFTR1715LWS

**Serial:** BA11612610

## **OBSERVATIONS**

All appliances were operational at the time of inspection.

# INSULATION AND VENTILATION

In accordance with the CAHPI Standards of Practice pertaining to Insulation and Ventilation Systems, this report describes the insulation and vapor retarders used in unfinished spaces when readily accessible and the absence of insulation in unfinished spaces at conditioned surfaces. Inspectors are required to inspect insulation and vapor retarders in unfinished spaces when accessible, ventilation of attics and foundation (crawl space) areas and mechanical ventilation systems, if present.

## COMPONENT DESCRIPTIONS

### **Attic Locations and Access**

**Attic Spaces:** One

**Attic Access Locations:** laundry room ceiling

**Insulation Locations:** Attic floor

### **Attic Floor Insulation**

**Insulation Type:** cellulose

**Insulation Measure:** 8 inches

**Insulation R-Value:** 28

**Vapor Retarder:** Polyethylene plastic

### **Wall Insulation**

**Insulation Type:** Fiberglass batting

**Insulation Measure:** 4 inches

**Insulation R-Value:** 12 - 15

**Vapor Retarder:** Polyethylene plastic

**Retarder Location:** Warm side of wall

### **Crawl space Insulation**

**Insulated:** joist bays and rim

**Insulation Type:** fiberglass bat

**Insulation Measure:** 8 inches

**Floor Insulation R-Value:** 24

**Under floor Barrier:** unknown

**Crawl space Barrier:** unknown



### **Attic Ventilation**

**Attic Ventilation Type:** Passive ventilation

**Attic Ventilation Intake Location:** Continuous soffit vents, cardboard baffles present

**Attic Exhaust Ventilation:** Roof vents and gable vents

### **Crawlspace Ventilation**

**Ventilation Type:** none – ok (conditioned space)<sup>1</sup>


### **House Ventilation**

**Exhaust Fans Devices:** bathrooms only

### **OBSERVATIONS**

The attic insulation level (R28 approx.) in the home is typical for dwellings this age. Nowadays they recommend attic insulation to be R40 -50.

The attic access hatch is not sealed nor insulated. This may cause some energy loss through convection. The warm air leaking into the attic area may further cause staining of the roof sheathing above the hatch area as it condenses on the cold roof sheathing and captures dust particles from the air. It is recommended that the hatch be weather stripped and insulated to the same approximate R value as the rest of the attic.



The roof / attic ventilation appears to be functioning normally and is adequate for a home of this size.

All bathroom fans functioned as designed at the time of the inspection.

*Inspectors are NOT required to determine indoor air quality or disturb insulation or vapor retarders, unless required by law.*

<sup>1</sup> There is no under-house ventilation for this home, as the crawlspace has been insulated and conditioned like a basement.

## FIREPLACES AND SOLID FUEL BURNING APPLIANCES

*In accordance with the CAHPI Standards of Practice pertaining to Fireplaces and Solid Fuel Burning Appliances, this report describes the fireplaces and solid fuel burning appliances as well as the chimneys. Those portions of the chimney(s) that extend above the roof are described under Roof System previously in this report. Inspectors are required to inspect system components, vent systems, flues and chimneys of fireplaces and solid fuel burning appliances.*

### COMPONENT DESCRIPTIONS

#### **Main Fireplace (between living and family room)**

**Fireplace Type:** masonry, wood-burning

**Fireplace Location:** between living and family room

**Supply Air:** from outside using air inlet built into firebox and by scavenging room air

**Fireplace Liner:** firebrick

**Hearth Style:** raised



#### **Second Fireplace (basement)**

**Fireplace Type:** freestanding wood stove w/masonry flue, label present. Date of manufacture and install: 2005 Owner has WETT inspection papers.

**Fireplace Location:** basement

**Supply Air:** by scavenging room air

**Fireplace Liner:** firebrick

**Hearth Style:** raised

### OBSERVATIONS

Both the wood burning fire place and wood stove were recently professionally cleaned (see enclosed copy of invoice). It is recommended to have a qualified technician inspect and clean fuel burning appliances annually, before the cold weather sets in, to ensure they are in good working order.

A carbon monoxide detector was noted on the wall near the basement wood stove. It is recommended to check it regularly to ensure it operates properly.

*Inspectors are NOT required to ignite or extinguish any fires in any device, determine the draft characteristics of vents or chimney flues, move fireplace inserts, stoves or firebox contents, inspect the interior of flues or chimneys, fire screens or doors, seals and gaskets, automatic fuel feed devices, combustion make-up air devices, mantels and fireplace surrounds or any heat distribution accessory devices, whether gravity controlled or fan assisted.*

# DETACHED GARAGE

---

## COMPONENT DESCRIPTIONS

### **Garage Features**

**Garage Attached:** Detached Garage and storage room

**Auto Bays:** three bay

**Location:** south side of the home

### **Garage Structure**

**Foundation Type:** poured concrete

**Wall stud:** 2 by 4

**Wall On-Center:** 16-inch

**Wall Covering:** plywood sheathing

**Wall Surface Material:** stucco

**Wall Trim:** wood

### **Roof System**

**Roof Assembly Type:** manufactured truss assembly

**Roof Sheathing:** oriented strand board (OSB)

**Roofing Materials:** asphalt/fiberglass shingles

**Gutter Downspout Type:** aluminum

### **Doors and Windows**

**Garage Door Type:** None

**Pedestrian door:** hollow wood into storage room

**Window Frames:** aluminum

**Windows Glazing:** double glazing

**Condition:** satisfactory condition

### **Insulation and Heat**

**Wall Insulation:** fiberglass batting

**Inside Wall Finish:** plywood and barn board

**Electrical and lighting:** none

# POOL

---

## COMPONENT DESCRIPTIONS

### Pool Description

**Pool Type:** 20 by 40 ft. in-ground salt water pool

**Pool Location:** south side of the home

**Pool material:** reinforced concrete shell

**Pool Finish:** plastered exposed aggregate

**Pool Surrounding:** poured concrete flatwork

**Pool Coping Material:** poured concrete

**Pool Fixtures:** one metal ladder, one walk-out set of stairs, one diving board and one solar blanket

### Electrical Controls

**Panel Location:** at a sub-panel near the equipment

**Amperage Rating:** 50 amps

**Voltage Rating:** 120/240 volts

**Breaker Fuse Style:** Breaker

**Pumps on Timer:** no

**Underwater Lighting:** 120-volt underwater      **GFCI Found:** Yes<sup>1</sup>

### Water Supply

**Water Supply Plumbing:** PVC plastic pipe

**Heat Source:** Gas heater (not connected) and solar blanket

**Filter:** sand filter

**Pumps:** circulation

### Gate and Fencing

**Fencing:** wood and wrought iron fencing and gates

**Fence Height:** at least 5 ft.

**Gate Opens:** inward

**Lock Height:** at least 48 inches

---

<sup>1</sup> GFCI are safety devices that sense a ground fault in an electrical system and cut power to a circuit faster than one's nervous system can react. Modern codes require any branch circuits at kitchen counters, in bathrooms, basements, garages or exterior outlets to be GFCI protected. The code at the time this home was built may not have required GFCI protection at these circuits. Nonetheless, we strongly recommend they be added at these locations as an extra preventive safety measure.

## **OBSERVATIONS**

Pool was up and running at the time of inspection.

Pool filters are not tested for function and functionality is excluded from the scope of the inspection.

While every effort is made to verify shell integrity, cracks in a pool liner are very difficult to see unless the water is drained from the pool prior to inspection. For this reason, crack detection in the liner is excluded from the scope of the inspection.

## **This concludes the Home Inspection Report.**

Please do not hesitate to contact me anytime with any questions or concerns. You may view additional photos taken during the inspection on the DVD enclosed within the binder. You can pop the DVD in your DVD player and view, or you can view and print from your computer.

Thank you for allowing me to inspect your home!

Yours truly,

Jeanine Reiss

FYI Home inspections LTD.

[www.fyihomeinspections.ca](http://www.fyihomeinspections.ca)

Cell/text: 250-864-4054

